Next 1 Page(s) In Document Exempt



COBA

		MISSION COORDINATOR CHECK LIST
	·	FROM: START 25×1A TO: (<u>//30</u>)
TIME (NLT)	RESP	ACTION COMPLETED
ASAP	DCOC 25X1A	Complete & distrubute mission alert 0845 notification
ASAP	DCOC	Acknowledge Receipt of 090025X1A
ASAP	DCOC	Convert H -hour time to local and 0700 record in check list.
ASAP	DCOC	Complete pilots activity schedule 0905 (5) (1-DCO, 1-M/C, 1-Flt Surg, 1-CO, 1-DCOL)
ASAP	дсос 25×1А	Notify & alet the C-130 (21 TCS) 0930L. Naha WA-7175 Lt Col 25X1A Advise that we have an airlift requirement to Yokota at 15/0830 Z. In place time here to pick up TAKE is L+2:00. 25X1A
ASAP	рсос 25Х1А 25Х1А	Check with DCOM to see if Msgs (74) 1045 have been received by 1004 prior to (81) 1525
ASAP	DCOC	check with DCOM FOR the check list 1000 to be used. (a) Custom or canned route.
		(b) Custom route w/option (Delete non-applicable items from M/6 Checklist i.e. DCOM (A) DOOM (B) 1000
ASAP	TTFC	Delivers tanker schedule with all //oc C/S - & timing.

Page 1

revised 16 Sept 67.

VAGOO	Approve	ed For Release	2002/06/10 : CIA-RDP69B00041R091300040005-6
			FROM: H -24:00(<u>-//30</u> L)
			TO: H -18:00(<u>/43</u> 0 L)
- (4)	TIME NLT	RESP	ACTION TIME
X1A	T 24.00(<u> </u>	
	H -23:30(L) DCOC/	M/C attend Commander's initial D85 priefing. Receive Ops personnel inputs for recovery team. Give to DCS. Prepare access lists for CP and Flt Following Room.
1A	H -23:00(/23	<u>(</u> L) SEC	Hangars secured, access lists 093
***	н -22:00(133	OL) COMMO	Recd repare Flimsy 090
	H -21:00(/43	L) Flt Surg	Results of pilot physicals 103
1A	H -21:00(<u>/430</u>	L) DCOC	Send
American Zing new war.	н -20:30(1566	COMMO	Notify DCM of Freq Channelization and translator code.
Specific v. 2. br. skindstand in	н -19:00(<u>/63</u> €	L) DCM	Complete TEB and Refuel (Item 8) #1 /430 * (Item 3) #2 /200
Д	н -19:00(_L) SEC	Advise M/C of Seat Kit No. Prm AC Kit /6 (Enter Bottom or Sec AC Kit /0)
	Н -19:00(_L) DCOM	Tape Recorders ready in briefing Rm /32
	н -19:00(_L) COMMO	Complete Commo flimsy, cys to: M/C-3, (2 Pilots + 1 CP) and DCOMF-2
and the second s	* DCM REGE	NERATION	
	`		



٠.			FROM: H-18:00 (<u>/</u> 4	(30 L)
		1	то: н-12:00 (<u>А</u>	0 <u>30</u> L)
	TIME (NLT)	RESP	ACTION	TIME
	H-18:00(<u>/730</u> L)	DCOMI	Start Intelligence Briefing	1730
	H-17:00(//3/30L)	DCO	Supervise Plt's Initial Briefing	1830
-	H-16:00(/930L)	DCM	Complete INS pre-flt (item 12) #1	1500
			25X1A #2	1030
,	H-15:00(2030L)	DCOM(A)	Receive (Via 1004)	1030
	H-15:00(<u>2030</u> L)	DCM	Deliver with EWS System Checkout Info.	NYA
	H-15:00(2635 L)	соммо	Deliver to M/C if all Info available.	Z355
	H-13:00(2236L)	DCM	Complete EWS Pre-Flt (Item 13) #1	1630
		•	#2	1615
	H-13:00(2230L)	DCOM(A)	INS Load Sheet. Deliver to INS	1200
	H-13:00(2236 L)	Flt Surg	Start Crew Rest 25×1A	<u>ZZ30</u>
	H-12:30(2366L)	DCOM	Notify M/C of receipt of Pkg Data) (Via 1004) 25X1A	1520
	H-12:00(<u>2330</u> L)	DCOC	Send upport Msg to 313th	1515
	H-12:00(2330L)	DCOM(A)	Receive Wea update flt plan (Via 1004)	2330
			1	



FROM: H-12:00 (2330L)

H- 2:00 (_0930_L)' TO:

	9	i i	
TIME(NLT)	RESP	<u>ACTION</u>	TIME
H-11:30(@000 L)	DCOM	Package program to Pkg personnel	2330
H- 9:00(<u>6230</u> L)	DCOW	M/C item (G) Wx effect of ability to launch. 25×1A	1200
H- 9:00(0230L)	BCOC	Send o Hqs 25X1A	2200
H- 8:30(<u>a 3oo</u> L)	DCM	Complete Pkg Load (Item 15) #1	2215
		#2	2320
H- 6:00(0530L)	DCOC	DCOM(B) advise 313th of Option	M
# 3+30(±)	DOCK(D)	Proceed today sheet to IND	
VI 5 00/ T)		7	
_ ,,	Doctiva		200
H- 4:30(<u>6 766</u> L)	DCOM(A)	Film strip complete	0600
H- 4:00(<u>0730</u> L)	AFCS	Report Equip status to DCOC	0630
H- 3:45(<u>6745L</u>)	CMDR DCO F/Surg	Final decision on primary & spare pilot, notify DCOL	0907
H- 3:45(0745L)	DCO	Current Airfield Status	0745
H- 3:30) 4 800 L)	DCM	Start INS Warm (Item 21) #1	0750
		*(Item 14) #2	0800
H- 3:30(0300 L)	DCO -	Final Briefing	0800
H- 2:30(0900 L)	DCOC	Send confirmation of	0215
		Coord.	

DCM REGENERATION

Page 4

Revised 15 September 1967



Page_5

	•	FROM: H -2:00 (<u>6936</u> L)
		TO: L HOUR (//_3.0L)
TIME (NLT)	RESP	ACTION TIME
H -1:30(/600 L)	DCOC	Notify Helicopter Section of ETD 1000
H -2:00(0930 L)	DCOMI	EEE Packet turned in to DCOL 0900
H -1:35(6955 L)	DCOW	Letdown plates to pilots Acry 1630
H-1.30(DOOM (B)	TIM SULLP COMPACT
		#2
H1:25(/005 L)	F/Surg	Pre-suiting physical
H -1:00(/030 L)	DCOM	Load DCOM material both acft #1/030
		#2 1030
H -0:50(/040 L)	DCOL	Pilot to aircraft /0 /0
H -1:00(/030 L)	DCO	Go-No-Go decision 1038
H -1:00(/030 L)	DCOC	Activate HF (CONTROLLER) 1030
H -1:00(/030 L)	DCOC	Check latest NOTAMS
H -1:00(/0 36 L)	DCOC	Assure Chopper alerted 1630
H -: 45(/0 45 L)	DCOL	Pilot hooked up in acft /6 4)
H -: 30(/// L)	DCM	Start engine 25X1A
H -:15(<u>///5</u> L)	DCOC	Cmdr's emerg C.L., Dash-1, CYG Ck ///S
H -:00(1/30 L)	DCOC	Send 25X1A 1/32 - 1/3
H Hour(//30 L)	DCOC	Send T/O. Msg to 313th. 1132-115
H+1:15(L)	DCO	Release spare (primary) N/A
:30 prior to ldg	DCOC	Alert chopper (controller)
:30 prior to ldg	DCOC	Notify Transit Alert (controller) 1520
:30 prior to ldg	M/C	Prepare for DTFC or DCO 14455X1A (clip bd) (primary)
ASAP after ldg	DCOC	Send (Msn ldg report) /5 4 25 X1A
ASAP after ldg *(****	. DCOC *****	Send 313th CNX (ATA) msg /547
Page 5 Approved For	Release 2	2002/06/10: CIA-RDP69B00041R001300040005-6ug 1967

Approved For Release 2002/06/10 : CIA-RDP69800041R001300040005-6 FROM: H +1:00 (TO: END TIME (NLT) RESP ACTION TIME SECONDARY LAUNCHED 25X1A ASAP DCOC Sen n Primary 25X1A ASAP DCOC Send abort Msg on Prim 25X1A H +1:00(L) DCOC Send n Secondary H +1:00(L) DCOC Send /O on Secondary L = :30(L)Notify Helicopter (controller) DCOC L -:30(L) DCOC Notify Trans Alert (controller) L Hour(L) DCOC Send 25X1A L Hour(L) DCOC Send Give ATA ********* ASAP after ldg ! DCOC Receive CYG Down time, then release /5 Notify TTFC. ASAP after ldg DCOC Release Helicopter (controller) ASAP after Ldg DCOC Release C-130 (21TCS) L +:30(L) AFCS Shutdown 25X1A L +1:30(L) DCOMI Par "C" of to DCOM L:+3:30(L) SEC Sterilize aircraft DCOC DCOM Release Acft to DCM Recording tape and film strip to Security. L +5:00(L) DCO Review Tanker Msn Report L +5:00(____L) **DCOM** Tape of debrief to Security

L +5:00(L)

COMMO

B/W Tape to Security

	الله برابية بالم لكية - الله الله الله الله الله الله الله الل			* * * * * * * * * * * * * * * * * * *			(of said	A Section of the second section of the section of the second section of the section of th	grams of the second of the sec
		25X1A		\mathcal{B}_{i}	167	39			*BLACKSHIELD*
25X1A	V		TITLE	LCL	E Z	_ IN	עניטס	ACTION	REMARKS
			Msn Alert Wx Fcst		-25	X		WX	(Receive Daily)
			Airfield Status	Dai	ly		X.	DCOC (Controll)	As of 0900L Filed in
			Tanker Msn Alert		24	Х		SAC	25X1A
			Mission Alert	ļ.	24	Х		CMDR/DCO	
			25×1A Ackd Receipt	ASA	P	ar .		DCOC	
			Mission Plan Wx Requirement		23	Х		wx/dco	
1			Opln Commo Data		22	X		COMMO/DCO	
•			EWS Setting		22	X	-	EWS	
6			Tanker/Wx Scout Recall Word		22	Х		SAC/DCO	
-			Mission Alert Confirmation	-2	21	-	х	DCO	
			Tanker Support		21 :		·X	SAC	

25X1A

PAGE 1

Approved For Release 2002/06/10 : CIA-RDP69B00041R001306040005-6

-21

-20

X

X

ısn Plan Wx Fost

Forward Base Wx

Wx Scout Request

Forecast

WX

WX

DCO

X

25X1A

Bypproved For Release 2002/06/10 : CA-RDP69800041R001300040005-6

X

DCOM

CODES

XEBU	A CONTRACTOR OF THE PROPERTY O	oproved Fo				YERO	ESO
	25×14		7	e i	-		*BLACKSHIELD*
	V	TITLE	LCL Z	IN	OUT	ACTION	REMARKS
	MR	Final Option Selection	-6 0530	X		DCOM	
		Msn Alert Wx Fost	-5 0630	х		WX	(Receive Daily)
		Emerg Seat Pack	-5 0630		Х	SECURITY	
		Forward Base Wx Forecast	-3 0830		х	wx	
		Met Watch Obs	0830		х	WX	
X1A	V	pord Confirmation	-3 0830	Х		DCO	
		GO-NO-GO Wx Forecast	0830	Х	2.5	ΜX	
	11/8	Spl Fuel Test	-2:30 0900		х	DCM(POL)	
X1A.	V	Coord Confirmation	-2:30 0°100		х	DCO	Submit to Hqs
	NR	Wx Scout Rpts	-2 0930	Х		WX i	Will be Received Continu Until AR Areas Secured
		Airfield Status	Daily O 900			COC (Controll)	25×1A As of 0900 Local Filed in
		Tanker T/O Rpt	As Req		х	SAC	Continous Until all Tank are Airborne
		GO-NO-GO Mags	1030	X -		DCO	* * * * * * * * * * * * * * * * * * * *

X DCO

Approved For Release 2002/06/10 : CIA-RDP69B0004180004200040066-667

Primary Take-off

Add Crew Number

Approved For Release 2002/06/10 : CIA-RDP6 B00041R001300040005-6 25X1A *BLACKSHIELD* TITLE IN OUT ACTION REMARKS ICL 5X1A Primary Take-off X DCO. CHANNELS As Req Primary Abort Χ DCO FLASH 25X1A As Req Primary Abort X DCO CHANNELS As Req Spare Take-off Х DCO Add Crew Number 25X1A As Req Spare Take-off X DCO CHANNELS As Req Tanker Off-load X DCO/SAC Continous Until All Fuel Rpt Off Loaded Primary Landing X DCO . Primary Landing 25X1A (Canx Support If Msn Completed) 25X1A DCO Х CHANNELS As Req Spare Abort X DCO FLASH 25X A Spare Abort As Req (Canx Support If Msn Cancelled) X DCO CHANNELS

25X1A

25X1A

Spare Landing X DCO pare Landing (Canx Support) X DCO ASAP

χ.

X

COMMO

SAC/WX

Approved For Release 2002/06/10 : CIA-RDP69B0004138000400058 67

ASAP

B/W Resume

Support Termination

Approved I	For Role ase	02/06/1	10 : CIA	-RDP69E	300041R0	# 13000400	05-6
· · · · · · · · · · · · · · · · · · ·	XERO				XEBO		
	gradicina da ser esta di			-1-	4 · · · · · · · · · · · · · · · · · · ·	in the state of th	

Was especially	· · · · · · · · · · · · · · · · · · ·	Apı	proved For Release 2	02/06/10 : CIA-	RDP	9B00	041200130	0040005-6
		25X1A						*BLACKSHIELD*
	V		TITLE	DUE LOL Z	- IN	OUT	ACTION	REMARKS
-	V		Msn Post Landing	L Plus 2	2 4 30 0000	X	DCO/CMDR	
			Tanker Landing	As Req		Х	SAC	Continuous Until all Tankers Have Landed
			Camera Config	L Plus 3		х	DCM	
	V		Mission Report	L Plus 3		x	DCO/DCOM	25×1A Info: "EYES ONLY CMDR"
			Spl Fuel Test	ASAP	,	х	DCM(POL)	
Boundary of the state of the st			Opnl Sortie Rpt	ASAP		х	DCO 11	Same as Nonop R-47
	V		INS Tape	ASAP		х	DCOMP	Via 1004 w/message back-up
			Take Progress	ASAP		x	SECURITY	
			Final Field Eval Of INS Data	L Plus 10		Х	DCM	
	(Flash Process	ASAP	Х		DCOMP !	
			Film Evaluation	ASAP	x		DCOMP	
			INS Tape Eval	ASAP	х		DCOMP	
			INS Film Correle.	L Plus 7 Days	Х		DCOMP	
			Systems VI TAKE PROGRESS RAT	ASAP		X .	SECURITY	
	PAGE	Apı	proved For Release 2	002/06/10 : CIA-	RDP	69B00	04 f300.150	0040095-667